

DC-DC Step-Up Converter

January 1999, 980073

Electrolytic capacitors C4 and C9 are shown with the wrong polarity in the circuit diagram,

Figure 1. The relevant PCB layout is all right.

Portable Sound-Pressure Meter

January 1998, 970085

The text alongside Figure 5 should be changed to read:

Measure the potential U_{REF1} , across pins 4 and 7 of IC2 and then connect a voltmeter across pins 4 and 7 of IC3.

Tachometer

October 1998, 980077

In the parts list and the circuit diagram, the value of R1 should be corrected to read 2.2 k Ω .